NYC-WTC_000430972

TAYLOR ENVIRONMENTAL GROUP — DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

TECHNICIAN	CLIENT	SITE ADDRESS	DATE SUBMITTED
TERESA MICHALCZUK	NYCSCA	~~STUYVESANT HS.~~ CHAMBERS ST, NY, NY	08.24.02
DATE SAMPLED	**CONTACT**	**WORK AREA**	**DATE LOGGED**
08.23.02	HAMID SAVAI	6TH FLOOR	
ROTOMETER NO.	**PROJECT NO.**	**PROJECT MANAGER**	**DATE APPROVED / SIGNATURE**
TEG-18	M477-15217-298884	G. TAYLOR	

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	~~F/CC~~ f/cc
6-C1		IWA ☐ EAST END OF CORRIDOR OWA ☐ BY STAIRWAY E	4/4	18.40	23.00	260	4	1040				<1.4
6-C2		IWA ☐ CENTER CORRIDOR OWA ☐ BY ROOM B 621	4/3	18.42	23.02	260	3.5	910				<1.6
6-C3		IWA ☐ WEST CORRIDOR OWA ☐ BY ROOM C 632	4/4	18.44	23.04	260	4	1040				<1.4
FB-1		IWA ☐ OWA ☐ FIELD BLANK-1										<1.5
FB-2		IWA ☐ OWA ☐ FIELD BLANK-2										<1.5
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED ~~TO TEG DROP BOX~~ (SIGNATURE)	DATE 8/24/2	TIME 1:30	RECEIVED FROM TEG DROP BOX (SIGNATURE)	DATE	TIME
RELINQUISHED BY: (SIGNATURE) Teresa M	DATE 08.24.02.	TIME 00 40.	RECEIVED BY: (SIGNATURE) R. Droudina	~~DATE~~ 8.24.02	~~TIME~~ 01.30
ANALYST: (SIGNATURE) R. DROUDINA	DATE 8.24.02	TIME 3.45AM.	COMMENTS 3 HR TAT FAX TO: 212-406-2535 # 516-358-1780		

CIRCLE: PCM TEM — BGRD PRE DURING POST — OSHA — OTHER

LOT # LOAT

FILTER MANUFACTURER ATC

WHITE: Office Copy YELLOW: ~~Lab Copy~~ PINK: Samples ORANGE: Site Copy

CITY_21MC100_010236508

NYC 9/11 Public Portal Document

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 08-26-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
6th Floor

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE 08-24-02
DATE RECEIVED: 08-24-02
DATE ANALYZED: 08-24-02

SAMPLE MEDIA: Air Samples
ANALYSIS REQUIRED: Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
6-L1	21460	East End of Corridor by Stairway E	<1.4	1.4
6-L2	21460	Center Corridor by Rm B621	<1.6	1.6
6-L3	21460	West Corridor by Rm C632	<1.4	1.4
FB1	21460	Field Blank	<1.5 µg	1.5 µg
FB2	21460	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC-WTC_000430973

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: AD

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000430974