TAYLOR ENVIRONMENTAL GROUP

DAILY MONITORING SHEET AND CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

TECHNICIAN: Waldemar Flouh	CLIENT: NYC SCA.	SITE ADDRESS: Stuyvesant H.S. Chambers St, NY, NY.	DATE SUBMITTED: 8.24.02
DATE SAMPLED: 8.23.02	CONTACT: Hamid Savoj	WORK AREA: 5th Floor	DATE LOGGED:
ROTOMETER NO.: L-21	PROJECT NO.: M477-15217-29884	PROJECT MANAGER: G. Taylor	DATE APPROVED / SIGNATURE:

SAMPLE & PUMP #	LABORATORY NO.	SAMPLE LOCATION, AREA & HEIGHT AND/OR EMPLOYEE	FLOW ON/OFF	TIME ON	TIME OFF	DURATION MINUTES	FLOW (AVERAGE)	LITERS	FIELDS	FIBERS	F/MM²	~~F/CC~~ mg/m³
5-L1		IWA ☐ OWA ☐ EAST END OF CORRIDOR BY STAIRWAY E	4/4	23.13	0325	252	4	1008				<1.5
5-L2		IWA ☐ OWA ☐ CENTER CORRIDOR BY ROOM C521	4/4	23.15	0327	252	4	1008				<1.5
5-L3		IWA ☐ OWA ☐ ~~WEST~~ CORRIDOR BY BOYS ~~BY STAIRWAY W~~ LOCKER RM	4/4	23.17	0330	253	4	1012				<1.5
FB-1		IWA ☐ OWA ☐ F/Blank-1										<1.5
FB-2		IWA ☐ OWA ☐ F/Blank-2										<1.5
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										
		IWA ☐ OWA ☐										

RELINQUISHED ~~TO TEG DROP BOX~~ (SIGNATURE): [signature]	DATE: 8.24.02	TIME: 6	RECEIVED FROM TEG DROP BOX (SIGNATURE):	DATE:	TIME:
RELINQUISHED BY: (SIGNATURE): [signature]	DATE: 8.24.2	TIME: 7:00	RECEIVED BY: (SIGNATURE): R. Droudina	DATE: 8.24.2	TIME: 7.00
ANALYST: (SIGNATURE): R. Droudina	DATE: 8.24.02	TIME: 09-20.	COMMENTS: Sheriff	Fax to 212-406-2535 516-358-1780	

CIRCLE: PCM TEM BGRD PRE DURING POST OSHA OTHER LOAD

LOT #

FILTER MANUFACTURER

WHITE: Office Copy YELLOW: Lab Copy PINK: Samples ORANGE: Site Copy

A+C

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE:	08-26-02
CLIENT:	Taylor Environmental Group, Inc.
PROJECT NAME:	SCA/Stuyvesant HS 5th Floor
PROJECT NUMBER:	M477-15217/29881
SAMPLED BY:	Client
SAMPLE DATE	08-23-02
DATE RECEIVED:	08-24-02
DATE ANALYZED:	08-24-02
SAMPLE MEDIA:	Air Samples
ANALYSIS REQUIRED:	Method NIOSH 7082

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/m^3$)	DETECTION LIMIT ($\mu g/m^3$)
5-L1	21462	5th Floor End of Corridor by Stairway E	<1.5	1.5
5-L2	21462	Center Corridor by Rm C521	<1.5	1.5
5-L3	21462	Corridor by Boys Locker Rm	<1.5	1.5
FB1	21462	Field Blank	<1.5 µg	1.5 µg
FB2	21462	Field Blank	<1.5 µg	1.5 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 3.0 µg
NOTE 2:
At the present time there are no regulatory levels or requirements for indoor airborne lead in area samples. However, OSHA has established an action level of 30 $\mu g/m^3$ and a permissible exposure level (PEL) of 50 $\mu g/m^3$ for personal samples.
NOTE 3:
Blank units are in µg

NYC-WTC_000430978

NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

CERTIFICATION AND SIGNATURES

ANALYSIS PERFORMED BY: RP

REPORT PREPARED BY:

ATC certifies that this report is an accurate and authentic report of results obtained from the laboratory analysis.

QUALITY ASSURANCE COORDINATOR:

LABORATORY DIRECTOR:

ATC is accredited by the New York State Department of Health Environmental Laboratory Approval Program (ELAP) and by the American Industrial Hygiene Association (AIHA) to perform analysis of lead in paint, dust wipes, air and soil samples. (ELAP #10879), (AIHA #100229).

NYC-WTC_000430979