NYC 9/11 Public Portal Document

ATC ASSOCIATES, INC
104 E 25th Street, 10th Floor
New York, NY 10010
Tel. 212-353-8280
Fax 212-353-8306

REPORT DATE: 07-26-02

CLIENT: Taylor Environmental Group, Inc.

PROJECT NAME: SCA/Stuyvesant HS
345 Chambers Street, NY

PROJECT NUMBER: M477-15217/29881

SAMPLED BY: Client

SAMPLE DATE: 07-26-02
DATE RECEIVED: 07-26-02
DATE ANALYZED: 07-26-02

SAMPLE MEDIA: Dust Wipe Sample
ANALYSIS REQUIRED: Method EPA 3050/7420

ANALYSIS RESULTS

SAMPLE ID	BATCH NO.	SAMPLE DESCRIPTION	LEAD CONCENTRATION ($\mu g/ft^2$)	DETECTION LIMIT ($\mu g/ft^2$)
DW-01	20676	10th Floor Supply Air Duct by Rm 1006	21.3	9.0
DW-02	20676	10th Floor Return Air Planum by Rm 1001	<9.0	9.0
DW-03	20676	10th Floor Supply Air Duct by Rm 1009	19.8	9.0
DW-04	20676	10th Floor Return Air Duct by Rm 1017	14.2	9.0
DW-05	20676	10th Floor Supply Air Dutc by Rm 1024	10.0	9.0
DW-06	20676	10th Floor Return Planum by Rm 1039	26.5	9.0
DW-07	20676	Field Blank	<9.0 µg	9.0 µg
DW-08	20676	Field Blank	<9.0 µg	9.0 µg

NOTE 1:
THE REPORTING LIMIT (RL) IS 18.0 µg
NOTE 2:
HUD Guidelines for final clearance dust wipe samples: Floor 40 $\mu g/ft^2$, Window sills 250 $\mu g/ft^2$, Window wells 400 $\mu g/ft^2$, Exterior surfaces 800 $\mu g/ft^2$.
NOTE 3:
Blank units are in µg